



FEEDER OUTAGES

<i>Feeders</i>	<i>Locations</i>	<i>Time Out</i>	<i>Time In</i>	<i>DURATION (MINUTES)</i>	<i>CLEARING DEVICE</i>	<i>CAUSE Code</i>	<i>Cause Description</i>	<i>COMMENT</i>
P341	Umatac to Santa Ana Agat	6/9/2008 7:37:00 PM	6/9/2008 8:02:00 PM	25	Line Breaker	50-ST	VEHICLES-Subtransmission	Dump truck crashed into power pole in Umatac. Lines isolated to remove dump truck. DDE lifted to isolate area
P341	Umatac to Santa Ana Agat	6/9/2008 9:49:00 PM	6/9/2008 10:06:00 PM	17	Line Breaker	50-ST	VEHICLES-Subtransmission	Crew to tie jumpers to restore the P-341 back to it's normal configuration.

GENERATOR OUTAGES

<i>Generators</i>	<i>Locations</i>	<i>Time Out</i>	<i>Time In</i>	<i>DURATION (MINUTES)</i>	<i>CLEARING DEVICE</i>	<i>CAUSE Code</i>	<i>Cause Description</i>	<i>COMMENT</i>
CABRAS 02	CABRAS	5/10/2008 10:22:00 PM			Generator Breaker	62	REPAIR	Scheduled shut down for unit # 2 for boiler over haul.
MACHECHE CT	MACHECHE	5/23/2008 5:30:00 PM			Generator Breaker	13	AUXILIARY SYSTEMS (provide details)	Turbine mounting bolts rusted off. Unit tagged out
TANGO 01	TANGUISSON	6/6/2008 11:33:00 AM			Generator Breaker	0		TANG. #1 Tripped Due To Boiler Tube Leak. / *** The Following 13.8 Kv Bkrs. Tripped On KF- Relay. P-202,204,262,330 And P-331.

Vicente Mesa, P.E.
Vicente Mesa, P.E.
PSCC Manager

Tuesday, June 10, 2008



TRANSMISSION/SUB TRANSMISSION OUTAGES

<i>Lines</i>	<i>Locations</i>	<i>Time Out</i>	<i>Time In</i>	<i>DURATION (MINUTES)</i>	<i>CLEARING DEVICE</i>	<i>CAUSE Code</i>	<i>Cause Description</i>	<i>COMMENT</i>
X039	APRA	6/9/2008 7:25:00 PM	6/9/2008 10:02:00 PM	157	Line Breaker	50	VEHICLES	Dump truck crashed into power pole in Umatac. Lines isolated to remove dump truck
X250	UMATAC	6/9/2008 7:26:00 PM	6/9/2008 10:04:00 PM	158	Line Breaker	50	VEHICLES	Dump truck crashed into power pole in Umatac. Lines isolated to remove dump truck


Vicente Mesa, P.E.
PSCC Manager