



FEEDER OUTAGES

<i>Feeders</i>	<i>Locations</i>	<i>Time Out</i>	<i>Time In</i>	<i>DURATION (MINUTES)</i>	<i>CLEARING DEVICE</i>	<i>CAUSE Code</i>	<i>Cause Description</i>	<i>COMMENT</i>
P003	Piti Cabras, Port Authority	6/19/2008 9:51:00 AM	6/19/2008 10:05:00 AM	14	Line Breaker	41	UNDERGROUND CONDUCTORS	C-541 Initial report was GWA back hoe dug into U/G line. 1005 P-3 restored up to Cabras Admin Bldg 1017 Kaiser Cement lateral isolated, Power restored to Port Authority. See comment on P-3 outage 11:11 AM
P003	Piti Cabras, Port Authority	6/19/2008 11:11:00 AM	6/19/2008 11:27:00 AM	16	Line Breaker	41	UNDERGROUND CONDUCTORS	While restoring Kaiser Cement lateral P-3 tripped, C-50 reports shorted conductor inside manhole on lateral feed to Foxtrot pier area 1127 lateral isolated, P-3 restored 1248 Kaiser Cement lateral restored
P313	GAA	6/19/2008 12:31:00 PM	6/19/2008 12:52:00 PM	21	Line Breaker	8	LIGHTNING	C-441 patrolled P-206/P-313 lines . Reports no finding, heavy lightning activity in area. Targets: Time on ground
P206	Tamuning Hafa Adai theaters to Airport Rd	6/19/2008 12:31:00 PM	6/19/2008 12:52:00 PM	21	Line Breaker	8	LIGHTNING	Note: P-206 backfeeding P-313. C-441 patrolled lines Reports no finding, heavy lightning activity in area.

GENERATOR OUTAGES

<i>Generators</i>	<i>Locations</i>	<i>Time Out</i>	<i>Time In</i>	<i>DURATION (MINUTES)</i>	<i>CLEARING DEVICE</i>	<i>CAUSE Code</i>	<i>Cause Description</i>	<i>COMMENT</i>
CABRAS 02	CABRAS	5/10/2008 10:22:00 PM			Generator Breaker	62	REPAIR	Scheduled shut down for unit # 2 for boiler overhaul.

Vicente Mesa, P.E.
Vicente Mesa, P.E.
PSCC Manager

Friday, June 20, 2008



MACHECHE CT	MACHECHE	5/23/2008 5:30:00 PM			Generator Breaker	13	AUXILIARY SYSTEMS (provide details)	Turbine mounting bolts rusted off. Unit tagged out
TANGO 02	TANGUISSON	6/20/2008 1:23:00 AM			Generator Breaker	13	AUXILIARY SYSTEMS (provide details)	Tango Unit 2 secured due to boiler tube leak.


Vicente Mesa, P.E.
PSCC Manager

Friday, June 20, 2008