




## FEEDER OUTAGES

| <i>Feeders</i> | <i>Locations</i>   | <i>Time Out</i>          | <i>Time In</i>          | <i>DURATION<br/>(MINUTES)</i> | <i>CLEARING<br/>DEVICE</i> | <i>CAUSE<br/>Code</i> | <i>Cause<br/>Description</i> | <i>COMMENT</i>                   |
|----------------|--|--------------------------|-------------------------|-------------------------------|----------------------------|-----------------------|------------------------------|----------------------------------|
| P323           | Pagat RTE 15,<br>GW/GCC area   | 6/12/2008<br>12:08:00 AM | 6/12/2008<br>1:14:00 AM | 66                            | Line Breaker               | 65-ST                 | UNKNOWN-<br>Subtransmission  | Loss of X-134/X-180 34.5 kv line |
| P322           | Pagat Latte<br>Heights/Plantation,<br>Los Palmas to<br>Santeena Mall | 6/12/2008<br>12:08:00 AM | 6/12/2008<br>1:14:00 AM | 66                            | Line Breaker               | 65-ST                 | UNKNOWN-<br>Subtransmission  | Loss of X-134/X-180 34.5 kv line |

## GENERATOR OUTAGES

| <i>Generators</i> | <i>Locations</i> | <i>Time Out</i>          | <i>Time In</i>           | <i>DURATION<br/>(MINUTES)</i> | <i>CLEARING<br/>DEVICE</i> | <i>CAUSE<br/>Code</i> | <i>Cause<br/>Description</i>              | <i>COMMENT</i>   |
|-------------------|------------------|--------------------------|--------------------------|-------------------------------|----------------------------|-----------------------|---|--|
| CABRAS 02         | CABRAS           | 5/10/2008<br>10:22:00 PM |                          |                               | Generator<br>Breaker       | 62                    | REPAIR                                    | Scheduled shut down for unit # 2 for boiler over haul.   |
| MACHECHE CT       | MACHECHE         | 5/23/2008<br>5:30:00 PM  |                          |                               | Generator<br>Breaker       | 13                    | AUXILIARY<br>SYSTEMS (provide<br>details) | Turbine mounting bolts rusted off. Unit tagged out   |
| TANGO 01          | TANGUISSON       | 6/6/2008<br>11:33:00 AM  | 6/12/2008<br>10:17:00 PM | 9,284                         | Generator<br>Breaker       | 13                    | AUXILIARY<br>SYSTEMS (provide<br>details) | TANG. #1 Tripped Due To Boiler Tube Leak. / *** The Following 13.8 Kv Bkrs. Tripped On KF- Relay. P-202,204,262,330 And P-331. |

  
 Vicente Mesa, P.E.  
 PSCC Manager

Thursday, June 12, 2008



**TRANSMISSION/SUB TRANSMISSION OUTAGES**

| <i>Lines</i> | <i>Locations</i> | <i>Time Out</i>          | <i>Time In</i>          | <i>DURATION<br/>(MINUTES)</i> | <i>CLEARING<br/>DEVICE</i> | <i>CAUSE<br/>Code</i> | <i>Cause<br/>Description</i> | <i>COMMENT</i>  |
|--------------|------------------|--------------------------|-------------------------|-------------------------------|----------------------------|-----------------------|------------------------------|---|
| X134         | MACHECHE         | 6/12/2008<br>12:08:00 AM | 6/12/2008<br>1:09:00 AM | 61                            | Line Breaker               | 65                    | UNKNOWN                      | No Findings. Targets: Inst Z-1 A&B phase, distance=<br>1.04 miles |

  
Vicente Mesa, P.E.  
PSCC Manager

Thursday, June 12, 2008