



FEEDER OUTAGES

<i>Feeders</i>	<i>Locations</i>	<i>Time Out</i>	<i>Time In</i>	<i>DURATION (MINUTES)</i>	<i>CLEARING DEVICE</i>	<i>CAUSE Code</i>	<i>Cause Description</i>	<i>COMMENT</i>
P220	Apra Heights to Tarzan Falls	6/25/2008 2:07:00 PM	6/25/2008 2:11:00 PM	4	Line Breaker	65	UNKNOWN	No findings. Targets: Instan on B & C phase.

GENERATOR OUTAGES

<i>Generators</i>	<i>Locations</i>	<i>Time Out</i>	<i>Time In</i>	<i>DURATION (MINUTES)</i>	<i>CLEARING DEVICE</i>	<i>CAUSE Code</i>	<i>Cause Description</i>	<i>COMMENT</i>
MACHECHE CT	MACHECHE	5/23/2008 5:30:00 PM			Generator Breaker	13	AUXILIARY SYSTEMS (provide details)	Turbine mounting bolts rusted off. Unit tagged out
CABRAS 02	CABRAS	6/25/2008 1:45:00 PM	6/25/2008 9:32:00 PM	467	Generator Breaker	62	REPAIR	Testing of unit after over haul. 06/26/08 0800 Unit remains at 10.0 mw
MEC 08	PITI	6/26/2008 7:35:00 AM			Generator Breaker	61	PREVENTIVE MAINTENANCE	1000 hour PMs and repair of bellows leak


Vicente Mesa, P.E.
PSCC Manager

Thursday, June 26, 2008



TRANSMISSION/SUB TRANSMISSION OUTAGES

<i>Lines</i>	<i>Locations</i>	<i>Time Out</i>	<i>Time In</i>	<i>DURATION (MINUTES)</i>	<i>CLEARING DEVICE</i>	<i>CAUSE Code</i>	<i>Cause Description</i>	<i>COMMENT</i>
X178	GIAT	6/26/2008 2:07:00 AM	6/26/2008 3:07:00 AM	60	Line Breaker	65	UNKNOWN	No findings. Targets:Z-1 . Inst on gnd, distance=. 3.6 miles
X081	HARMON	6/26/2008 2:07:00 AM	6/26/2008 3:07:00 AM	60	Line Breaker	65	UNKNOWN	No findings. Targets: Z-1 . Inst on gnd, distance=. 2.66 miles


Vicente Mesa, P.E.
PSCC Manager

Thursday, June 26, 2008